




3-Step Program

1.2.3

ICE TREATMENT

Removes Contaminants and Restores Clarity



Step 3

Net Weight: 32 Ounces

The ultimate cold plunge system!
Following the ICE Program ensures
clean, clear healthy water.

ICE TREATMENT works in conjunction with regular draining
and cleaning using ICE CLEAN (Step 1) and an ICE MINERAL
CUBE (Step 2) whenever the plunge tub is filled with water.

ICE TREATMENT Directions:

- Add 5 ounces of ICE TREATMENT per 100 gallons
of water to the plunge tub once a week.
- Allow water to circulate for 15 minutes.*
- Test weekly for pH and Peroxide Levels.
The proper pH is 7.2 - 7.6 ppm.
Peroxide should be 50 - 90 ppm.

*If the Plunge Tub is unfiltered, thoroughly mix ICE
TREATMENT into the water until dissolved.

The use of Hydrogen Peroxide reduces contaminants
in the water through oxidation. ICE TREATMENT is safe
on skin, hair and swimwear when diluted in water.

WARNING: For external use only. Point bottle away from face when
removing cap. Avoid direct contact with eyes and skin except when
diluted in water. If contact occurs, flush with water. Call a physician
or poison control center if swallowed. Does not contain chlorine.

KEEP OUT OF REACH OF CHILDREN

Ingredients:
Hydrogen Peroxide Formulated for Cold Plunge Use
Rapid Dissolve



ITEM 2718
149-038413S12
998-MH1100G01
Rev No. 0325

ESSENTIALS
5070 Wallace Drive • Cumming, GA 30041

www.Essentials-SpaSupplies.com

Made in the USA



30 oz _____

28 oz _____

26 oz _____

24 oz _____

22 oz _____

20 oz _____

18 oz _____

16 oz _____

14 oz _____

12 oz _____

10 oz _____

8 oz _____

6 oz _____

4 oz _____

2 oz _____